


BK 89 PG 2

# CORNER RECORD

Document Number CR 9230

City of SAN LEANDRO County of ALAMEDA, California

Brief Legal Description DAVIS ST. AND EAST 14TH ST.



## CORNER TYPE

Government Corner ☐ Control ☒  
 Meander ☐ Property ☐  
 Rancho ☐ Other ☐  
 Date of Survey 10/11/2016

## COORDINATES (Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ NAD27 ☐ NAD83 ☐  
 NAD83 Epoch \_\_\_\_\_  
 Elev. \_\_\_\_\_  
 Vet. Datum: NGVD29 ☐ NAVD88 ☐  
 Meas. Units: Metric ☐ Imperial ☒

Corner — Left as found ☒ Found and tagged ☐ Established ☐ Reestablished ☐ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND 2-1/2 INCH DIAMETER BRASS DISK WITH PUNCH. STAMPED 'ALAMEDA COUNTY R/S 662 LS 5105'

LOCATED IN MONUMENT WELL AT INTERSECTION OF DAVIS ST. AND E 14TH ST.

A description of the physical condition of the monument as found and as set or reset: \_\_\_\_\_

SET NAIL AND TAG, STAMPED LS 8593 AS REFERENCE POINTS TO BE USED TO RESET MONUMENT SHOULD IT

BE DISTURBED DURING CONSTRUCTION ACTIVITIES.

SEE SHEET 2 FOR GRAPHIC

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on OCTOBER 17, 20 16

Signed [Signature] P.L.S. or R.C.E. No. \_\_\_\_\_ L.S. # 8593

## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 3 NOVEMBER 20 16

and examined and filed 16 DECEMBER 20 16

Signed Michael Rubner P.L.S. or R.C.E. No. 6843

Title COUNTY SURVEYOR

County Surveyor's Comment: \_\_\_\_\_

